



Fluor Canada Ltd.
1075 West Georgia Street
Vancouver, B.C. V6E 4M7
Canada

604.488.2000 tel
604.488.2010 fax
www.fluor.com

Mining & Minerals

File No.: 102.1R-0000
Fluor Contract No.: A4VI
Letter No. A4VI-FVL-0000
Vale Inco Distribution Code:

Date – September 16, 2013

To Whom it May Concern

Re: MBI Corexcel

I am pleased to report that the safety performance of MBI Corexcel at the Long Harbour Processing Plant project was exceptionally good. The Safety Lead Jacques Quellet was very instrumental in the success of this company's safety performance. The work performed by MBI Corexcel was challenging in many respects from Confined Space Entries to working with sensitive materials used for bonding. MBI Corexcel worked very closely with all contractors in the areas of construction to ensure they were well aware of the conditions they might be exposed to and put the necessary controls in place to minimize the effects.

I credit this company's success to good management and safety planning and their performances reflects these efforts.

Sincerely,

FLUOR CANADA LTD.

Kevin McDonald
Sr. HSE Manager
Fluor Canada Ltd.
709-758-8819